



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 11/09/2026

Incharge(s): M Kailash

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-21	Reported Right Luff not working. Found control MCB is in OFF condition	Made ON	00:40:00	00:50:00	
2	OHP	WOBR on CO-29	LT not working. Found ACB is in tripped condition	Made ON and given clearance	23:15:00	23:35:00	
3	OHP	CO-26	Overload acted	Reset done	02:35:00 03:05:00	02:45:00 03:15:00	
4	OHP	CO-3B	BRS not resetting. Found module problem	Bypassed	01:15:00	01:30:00	
5	CHP	SCR-7, CC-40	TUL chute sensor and Belt sway kept in Bypass as per operation request	.	23:20:00	06:00:00	Kept in circuit at the end of shift
6	CHP	SCR-9	Luff not working	Found 24v Main solenoid valve output glass fuse blown. Replaced	23:15:00	23:30:00	
7	CHP	RECL-1	Boom conveyor not running	Found coal jamming near Bucket wheel. Informed to operation	00:40:00	00:50:00	
8	CHP	SCR-8	All Drives not working. Found ACB tripped	Made ON and tested operations	02:30:00	02:45:00	
9	CHP	SCR-9	Slew not working	wrong complaint	03:25:00	03:35:00	
10	CHP	SCR-8	Boom conveyor not running. Found chute jam	Informed to operation	03:40:00	03:50:00	
11	CHP	SCR-3	Boom conveyor not running. Found MPR tripped	Reset done	04:00:00	04:15:00	
12	CHP	RECL-1	Slew not working. Drive trip	Reset done	04:50:00	05:05:00	
13	CHP	STK-2,CC-3 5	Boom conveyor not running. MPR tripped due to overload.	Reset done	05:10:00	05:20:00	
14	CHP	STK-1	PCRD cable found Zigzag.	Unwinding done and made proper	22:25:00	22:45:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 11/09/2026

Incharge(s): M Kailash

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
15	CHP	TT on CC-28	Flap gate not working. Found TT power one phase missing	Checked and found four pole isolator one pole problem. Bypassed and given clearance.	00:30:00	01:20:00	changed the isolator
16	CHP	CC-52	MPR tripped	Reset done	00:45:00 22:15:00	00:50:00 22:20:00	