



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 07/10/2026

Incharge(s): Saurabh Kumar Yadav

Shift: B

| Sl No | Area | Equipment     | Problem                                                | Action                           | From     | To       | Remarks |
|-------|------|---------------|--------------------------------------------------------|----------------------------------|----------|----------|---------|
| 1     | OHP  | wobr on co 26 | LT not working,M3 mpcb was tripped                     | made on                          | 18:28:00 | 18:34:00 |         |
| 2     | OHP  | TBS on co 7A  | reported LT not working,wire opened in selector switch | properly connected in Remote s/s | 16:25:00 | 16:35:00 |         |
| 3     | OHP  | BRC on CO 32  | LT not working,OT acted                                | Ot released                      | 17:50:00 | 18:10:00 |         |
| 4     | OHP  | CO 25         | OLR acted                                              | reset                            | 19:10:00 | 19:20:00 |         |
| 5     | OHP  | TBs on Co 19  | Lt not working,M4 mpcb tripped                         | reset                            | 19:20:00 | 19:35:00 |         |
| 6     | IOSA | WOBR(L and T) | mains not getting on,ACB is in off condition           | ACB made on                      | 15:00:00 | 15:15:00 |         |