



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/09/2026

Shift: A

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VF-10A	OLR ACTED	RESET DONE	06:15:00	06:30:00	
2	OHP	WOBR- ON CO-6A	B/C ZSS PROBE PROBLEM	ZSS PROBE REPLACED WITH NEW ONE THAN OK	06:40:00	07:00:00	
3	OHP	BRC ON CO-28	REPORTED B/W-1 NOT RUNNING FOUND POWER MCCB TRIP	MADE ON THAN OK	08:00:00	08:25:00	
4	OHP	TBS ON CO-24	C/S ACTED DUE TO CHUTE JAMMING	AFTER CLEAR THE MATERIAL C/S RESET THAN OK	08:30:00	08:45:00	
5	OHP	BRC ON CO-28	REPORTED B/W-1 NOT RUNNING FOUND POWER MCCB TRIP DUE TO MOTOR POWER CABLE BURNT OLD JOINT	JOINT DONE THAN OK	09:10:00	10:50:00	RAIN WATER ENTER INTO OLD JOINT DUE TO CABLE BURNT
6	OHP	BRC ON CO-30	LT NOT TAKING PLACE FOUND M-6 OLR ACTED	RESET DONE	11:15:00	11:25:00	
7	OHP	RSCO-6A (C)DRIVE	OLR ACTED DUE TO TRACK JAMMING	RESET DONE	12:10:00	12:25:00	
8	OHP	CO-56	ZSS PROBE CABLE GOT CUT	RE-JOINT DONE THAN OK	12:25:00	12:40:00	
9	OHP	TBS ON CO-5A	LT M-4 OLR ACTED	RESET DONE	12:25:00	12:45:00	
10	OHP	CO-26	OLR ACTED	RESET DONE	12:55:00	13:05:00	
11	CHP	SCR 8 on CC 112	B/C chute sensor acted	Bypassed	10:25:00	10:35:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/09/2026

Incharge(s): K SANKARA RAO

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	CC 112	Drive end chute sensor acted	Cleaned the insulator and given clearance	07:20:00	07:30:00	
13	CHP	SCR 6 on CC 38	B/C chute sensor acted	Bypassed	09:10:00	09:20:00	
14	CHP	SCR 6 on CC 38	ZSS probe damaged	Replaced probe and given clearance	09:10:00	09:30:00	
15	WT	OT-1	DRIVE-1 TRIP (2TIMES)	RESET DONE	08:00:00	08:15:00	