



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/07/2026

Incharge(s): P Venkat Kiran,P Venkat Kiran

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-1a	pull chord is checked, found acted in tunnel area, reset done.	restored back in circuit.	06:30:00	06:45:00	
2	CHP	cc-28	olr acted	reset done	11:25:00	11:35:00	
3	CHP	cc-131	olr acted	reset done	11:00:00	11:10:00	
4	CHP	scr-1 on cc-31	boom conveyor not starting	slew 30deg limit acted and olr acted due to jamming, reset done and slew done.	09:35:00	09:45:00	
5	WT	op-3	top c clamp bent	replaced c clamp	12:20:00	12:40:00	
6	WT	op-4	not moving , D-4 tripped	reset done	11:40:00	11:50:00	