RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 22/10/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO 20	LT not working,due to M4 OLR	reset	22:20:00	22:35:00	
2	OHP	CO 25	OLR acted	reset	22:40:00	22:55:00	
3	OHP	VF1A	OLr acted	reset	22:30:00	22:40:00	
4	OHP	TT3 on co 16	LT not working,power mpcb tripped,pcrd cable tightened	mpcb made on,pcrd cable adjusted	04:45:00	05:15:00	
5	OHP	co 26	olr acted	reset	00:20:00	00:25:00	
6	OHP	TBS on co 21	pcrd fault,guide problem	informed mech,drum arrested	03:30:00	03:45:00	
7	OHP	CC 28	OLr acted	reset	23:50:00	00:00:00	
8	CHP	CC 15	olr acted	reset	22:30:00	22:40:00	
9	CHP	CC 35 STK2	LT not working,M1 tripped	reset	23:10:00	23:20:00	
10	CHP	CC 104 scr9	luff not working,110 v common high fuse blown	fuse replaced	04:35:00	04:50:00	
11	WT	OP 10	PLC DI and DO card showing error	12 slot rack back plane and DI ,DO card replaced than ok	22:00:00	01:00:00	PLC pinging intermittent ,to be checked ethernet cable from wireless modem to PLC(no delay)