



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 10/10/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment            | Problem                                        | Action                   | From     | To       | Remarks |
|-------|------|----------------------|------------------------------------------------|--------------------------|----------|----------|---------|
| 1     | OHP  | co 25                | olr acted                                      | reset                    | 17:20:00 | 17:28:00 | 2 times |
| 2     | CHP  | CC 106<br>SCR8       | slew and b/w not working,oil level low         | informed mech            | 18:15:00 | 18:25:00 |         |
| 3     | CHP  | CC 40<br>SCR7        | b/c not working                                | checked and found all ok | 18:50:00 | 19:00:00 |         |
| 4     | CHP  | CC 28 TT             | not working,mccb is in off                     | made it on               | 20:50:00 | 21:00:00 |         |
| 5     | CHP  | CC 203               | olr acted                                      | reset                    | 21:20:00 | 21:30:00 |         |
| 6     | CHP  | CC 54                | olr acted                                      | reset                    | 20:05:00 | 20:10:00 |         |
| 7     | CHP  | CC 114               | PC acted                                       | reset                    | 15:10:00 | 15:20:00 |         |
| 8     | IOSA | FLS wobr<br>on oc17a | bc not running,zss cage yard interlock problem | stone removed form cage  | 17:30:00 | 17:40:00 |         |