



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 10/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	OLR acted	reset done	03:30:00 04:45:00	03:40:00 04:55:00	
2	OHP	BRC on CO-30	Bridge conveyor not running. OLR acted	Reset done	00:00:00	00:10:00	
3	OHP	BRC ON CO-32	LT not working. PCRD Tension acted	Released and made OK	23:30:00	23:40:00	
4	OHP	TBS ON CO-19	LT and Right boom not working	LT found in local. kept in Remote. B/C OLR acted. Reset done	05:05:00	05:20:00	
5	OHP	BRC ON CO-8A	Bucket wheel rotating in full speed when pump started without bridge conveyor running	Solenoid plugs, XMD fues TBs to pump command opened and checked. But still bucket wheel is rotating. Informed to mechanical	05:05:00	06:00:00	pending
6	CHP	CC-51	MPD tripped to stop feeding conveyor	Reset done	22:25:00	22:30:00	
7	CHP	CC-58	Tripped on OLR	reset done	04:50:00	05:10:00	
8	CHP	CC-31	OLR acted	Reset done	23:40:00	23:50:00	
9	CHP	SCR-2 ON CC-33	Boom conveyor running signal not coming. Signal missing	LT done and made OK	00:40:00	00:55:00	
10	CHP	CC-32	OLR acted	Reset done	03:50:00	04:00:00	
11	CHP	SCR-1 on CC-31	Boom conveyor not starting due to 30 deg slew limit acted	Released and made OK	04:35:00	04:50:00	
12	CHP	CO-110	Pullcord unhealthy.	Bypassed	00:45:00	00:55:00	to be checked
13	CHP	CC-28,CC-29	Became unhealthy while checking Chute sensor bypass	Bypass removed and given clearance.	22:10:00	22:30:00	Feedback to be checked



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 10/10/2026

Incharge(s): M Kailash

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	COB-5 HMI	pop up not showing for conveyors.	System restarted and made OK	22:30:00	23:10:00	