



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 25/04/2026

Shift: C

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-6	Reported P/C not coming healthy	Bypassed at CJB	00:15:00	00:25:00	To be checked
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	00:00:00 22:30:00	00:10:00 22:40:00	
3	OHP	CO-29	Reported tripped	OLR acted.Reset done	00:10:00	00:20:00	
4	OHP	WOBR on CO-26	Reported LT not taking place	PCRD tension acted.Released and tested okay	04:30:00	04:45:00	
5	OHP	WOBR on CO-6A	Reported no operations taking place	Checked and found operator cabin rack 3 O/P cards not healthy.Replaced with bottom O/P cards but still not healthy.Back place replaced and tested okay	23:45:00	01:45:00	
6	OHP	Cc-117	TT reported no movement	TT power supply in off condition.Made on.	02:15:00	02:30:00	
7	CHP	CC-31 SCR-1	Slewing not taking place	Drive tripped.Reset done	03:25:00	03:35:00	
8	CHP	Cc-13	ZSS acting	Cage stuck.Made free and tested okay	02:10:00	02:20:00	
9	CHP	CC-54	Reported tripped	OLR acted.Reset done	23:50:00	23:55:00	
10	CHP	Cc-58 TT	CJD not healthy	Bypassed and then checked and cable found damaged.Cable rejoint done and kept in line	23:16:00	00:00:00	
11	CHP	Cc-116	ZSS acting	Bypassed and then module changed and kept in line	22:35:00	23:30:00	
12	CHP	Cc-132	P/C acted	Physically on one pc found in acted condition.Reset done and clearance given	04:10:00	04:20:00	
13	WT	OP-4	Reported not moving	D-3 OLR acted.Reset done	05:25:00	05:35:00	