



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/04/2026

Incharge(s): Saurabh Kumar Yadav

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CR 2	lube oil flow not ok	reset	16:10:00	16:15:00	
2	OHP	CO 9A	brs acted,no power,fuse blown in cjb	fuse replaced	19:40:00	20:00:00	
3	OHP	wobr on co 29	b/c not running,b/w stone stucked	wrong complaint	15:30:00	15:40:00	
4	OHP	CO 26	olr acted	reset	20:25:00	20:35:00	
5	OHP	TT3	position on co 8A,not coming,sensor problem	bypassed in i/o rack	21:20:00	21:25:00	
6	CHP	CC 58	motor tripped in olr	reset	17:20:00	17:35:00	
7	CHP	CC 26 A	olr acted	reset	16:40:00	16:45:00	
8	CHP	CC 201	pC acted,	released PC	14:30:00	14:40:00	
9	CHP	CC 31 Scr 1	slew not working,drive tripped	reset	20:10:00	20:20:00	
10	CHP	CC 201 and 204	mpd acted due to ol	reset	19:15:00	19:25:00	