



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 27/09/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-58	Reported tripped	MPCB tripped.Reset done	15:40:00	15:50:00	
2	OHP	BRC on CO-32	Lt not taking place	PCRD tension acted.Released and tested okay	18:20:00	18:35:00	
3	OHP	CO-25	Reported tripped	OLR acted.Reset done	17:20:00 18:40:00	17:30:00 18:50:00	
4	OHP	CO-29	Reported tripped	OLR acted.Reset done	18:35:00	18:40:00	
5	OHP	TIS-1,2,3	Not running	TIS-1 found coupling belt moving freely and gearbox no movement. TIS-2 Coupling belt is rubbing and not rotating freely and motor is tripping. TIS-3 MPCB aux block loose.Tightened and tested okay	17:00:00	18:00:00	Informed to operation and mechanical
6	OHP	CO-15	ZSS acting	Cage stuck.Made free	17:30:00	18:20:00	Belt type ZSS cages to be made ready.No cage available
7	CHP	Cc-58	Reported tripped	MPD tripped on current sp fault.Reset done	16:30:00	16:45:00	
8	CHP	Cc-131	Reported tripped	OLR acted.Reset done	20:25:00	20:30:00	
9	CHP	Cc-51A	Reported tripped	OLR acted.Reset done	18:35:00	18:40:00	
10	CHP	CC-9	Dewatering pump not working	Emergency PB acted.Released and tested okay	15:30:00	15:45:00	
11	CHP	CC-24	ZSS acted	Material stuck.Made free	15:20:00	15:30:00	