



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/05/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CR1A	zss problem,probe damaged	changed from 3A but that was also not working,module replaced ,finally bypass	23:00:00	00:01:00	spare probe not available
2	OHP	Co 25	OLr acted	reset	22:30:00	22:40:00	
3	OHP	WOBR on Co 26	slew not working, drive tripped	reset	22:25:00	22:40:00	
4	OHP	TBs on CO 7A	LT not working,drive tripped	reset	00:00:00	00:20:00	
5	OHP	CO 25	motor not running,motor W1 lug got melted and cut	lug replaced and given clearance	00:00:00	02:00:00	
6	OHP	TBS on Co 23	LT not working,no power,3 nos of HRC fuse blown,moisture and crack observed in coupler,Breaker tripped in 1-2LBDS5	isolator made off, coupler opened packing provided slipring side,megger done ,found value ok, hot blowing done both side of coupler,pin fixed and coupler fixed, space heater made on both side ,HT fuse replaced and isolator made on,breaker made on in 1-2lbs PNL no 23	01:20:00	05:30:00	NO spare HT fuse available
7	OHP	WOBR on CO 25	LT not working,M3 mpcb tripped	made it on	05:45:00	06:00:00	
8	CHP	CC 40	mpr acted due to overload	reset	22:40:00	22:45:00	
9	CHP	CC 38 scr5	slew not working ,emergency acted	released	00:45:00	00:55:00	
10	CHP	CC 40 SCr6	slew not working in stacking,30 degree limit acted	limit released	02:40:00	02:50:00	
11	CHP	CC 37 SCR3	LT not working,drive tripped	reset	01:38:00	01:45:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/05/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	CC 32	conveyor not running,mpd acted	reset	04:25:00	04:32:00	
13	CHP	CC 51	MPD acted 4 times	reset	01:30:00	01:35:00	
14	CHP	CC 51	olr acted	reset	02:40:00	02:45:00	2 times
15	CHP	CC 131	motor tripped in ol	reset	03:40:00	03:45:00	
16	CHP	CC 130	MD malfunction,found boulder on belt	informed operation	01:40:00	01:50:00	
17	WT	OT 3	D2 tripped 5 times	reset and mechanical adjusted the brake	03:20:00	03:30:00	