



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 18/09/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 29	olr acted	reset	14:35:00	14:45:00	
2	OHP	WOBR on co 6A	LT not working,s/s not selected in remote	kept in remote	15:30:00	15:50:00	
3	OHP	wobr on co 25	slew not working,olr acted	reset	16:55:00	17:15:00	
4	OHP	RSCO 6A(B and C)	OLR ACTED	reset	17:55:00	18:05:00	
5	OHP	TBS on CO21	c/s not working	wrong complaint	18:15:00	18:30:00	
6	OHP	co 26	olr acted	reset	18:35:00	18:45:00	2 times
7	OHP	CC 33 scr2	luff not working,olr acted	reset	19:25:00	19:35:00	
8	CHP	cc112 SCR8	slew not working,pump not getting on	upper house PLC relay pickup lower house not pickup,manually pressed K8 than slew working,after that k8 relay pickedup	18:10:00	18:45:00	core to be checked from upper house to lower house
9	CHP	CC 36 S1	LT not working,OT acted	OT released	19:50:00	20:05:00	
10	WT	OT1	not healthy,brake power mccb is in off condition	made it on	17:25:00	17:30:00	
11	IOSA	OC 14A	motor tripped due to ground fault	reset, motor megger done found 50 M ohm value	18:00:00	19:10:00	