वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 19/10/2026

Shift: A

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR ON CO 26	SLEW NOT TAKING PLACE/M1 TRIPPED ON OLR	RESET DONE	07:40:00	07:50:00	
2	OHP	VF 10A	TRIPPED ON OLR	RESET DONE	13:15:00	13:25:00	
3	CHP	cc 111	drive end C/S ACTED DUE TO JAMMING	RESET DONE AFTER CLEANING	07:10:00	07:25:00	
4	CHP	CC 26A	CHUTE POSITION SIGNAL NOT GETTING TO CCR	SENSOR CABLE GOT DAMAGED/BYPASSED	11:30:00	11:45:00	CABLE TO BE CHANGED
5	CHP	CC 107	BSS ACTED/RF SWITCH NOT GETTING RESET	BY PASSEDE AT I/O RACK	13:40:00	13:55:00	