



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/07/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	Reported tripped	OLR acted.Reset done	01:20:00	01:30:00	
2	OHP	Cr-3A	Reported permissive not healthy	Lubrication return oil flow red.Reset done at panel near crusher and tested okay	00:30:00	00:40:00	
3	OHP	VF-1A	Reported not running	Checked and found CS acted.	01:34:00	01:45:00	Informed to operation
4	CHP	CC-125	Reported tripped	OLR acted.Reset done(3 times)	00:22:00 01:40:00 03:25:00	00:27:00 01:45:00 03:30:00	
5	CHP	RG-2 F/G	Reported not moving	OLR acted.Reset done	04:20:00	04:25:00	
6	CHP	CC-26 on CC-22A	Signal missing	Checked and found TT placement not proper.Properly placed and tested okay	23:20:00	23:30:00	
7	CHP	CC-14	Reported tripped	OLR acted.Reset done	04:00:00	04:10:00	
8	WT	OT-3	Reported not rotating	D-1 tripped on encoder 43 fault.Reset done	02:55:00	03:00:00	