



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/07/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 29	TRIPPED ON OLR	RESET DONE	06:20:00 09:40:00	06:30:00 09:50:00	
2	OHP	TT 1 ON CO 14	LT NOT TAKING PLACE	CONTROL FUSE BLOWN(110V AC)	07:05:00	07:25:00	
3	OHP	TBS ON CO 22	LBC NOT RUNNING/ZSS PROBE DIRECTED	PROBE REPLACED THEN OK	08:40:00	09:00:00	
4	OHP	WOBR ON CO 26	LT NOT TAKING PLACE/	FAULT RESET DONE	08:50:00	09:10:00	
5	OHP	WOBR ON CO 26	BC NOT RUNNING/CHUTE SENSOR ACTED	PROBE CLEANED THEN OK	10:15:00	10:30:00	
6	CHP	CC-201	OLR ACTED	REST DONE	13:00:00	13:10:00	
7	CHP	CC-54	OLR ACTED	RESET DONE	09:50:00	10:00:00	
8	CHP	CC-58	CURRENT SP FAULT	REST DONE	09:30:00	09:40:00	
9	CHP	SCR-3 ON CC-37	REPORTED B/C STOPPING ON ZSS CHECKED AND FOUND ZSS PROBE DAMAGED	ZSS PROBE REPLACED WITH NEW ONE THAN OK	06:20:00	06:35:00	
10	CHP	SCR-2 ON CC-33	LT NOT TAKING PLACE DRIVE TRIP	RESET DONE	12:35:00	12:45:00	
11	WT	OP-4	DRIVE -2 TRIP	RESET DONE THAN OK	09:50:00	09:55:00	