



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/09/2026

Shift: A

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-34	OLR ACTED (2TIMES)	RESET DONE	08:10:00 08:30:00	08:15:00 08:35:00	
2	OHP	CO-20	REPORTED FAIL TO START CHECKED AND FOUND OUT PUT COMMEND RELAY COIL WIRE LOOSE	PROPERLY TIGHT THAN OK	11:45:00	12:05:00	
3	OHP	OF-1, 68A	REPORTED RUN FEEDBACK NOT COMING IN OCR CHECKED AND FOUND 1-15LC-2 RIO PANEL HIGH WIRE LOOSE	PROPERLY TIGHT THAN OK	13:30:00	14:00:00	
4	CHP	CC-33.SCR-5	REPORTED LT NOT TAKING PLACE FOUND PCRD O/T ACTED	RELEASED THAN OK	06:45:00	07:00:00	
5	CHP	CC-36 SCR-3	REPORTED LT NOT TAKING PLACE FOUND DRIVE TRIP (OVN FAULT)	RESET DONE	11:45:00	12:00:00	