



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 06/08/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

| Sl No | Area | Equipment      | Problem                                              | Action                                                                            | From                 | To                   | Remarks                                 |
|-------|------|----------------|------------------------------------------------------|-----------------------------------------------------------------------------------|----------------------|----------------------|-----------------------------------------|
| 1     | OHP  | co-26          | olr acted 2 times                                    | reset done                                                                        | 08:00:00<br>08:30:00 | 08:10:00<br>08:40:00 |                                         |
| 2     | OHP  | brc-3 on co-34 | It not taking place                                  | pcrd overtension acted                                                            | 07:50:00             | 08:05:00             | released                                |
| 3     | OHP  | wbr-2 on co-29 | It not taking place                                  | Drive tripped on OL due to track jamming                                          | 09:00:00             | 09:00:00             | reset done and informed agency          |
| 4     | CHP  | CC 104         | BRS ACTED                                            | Moisture entered into module.Hot blowing done and kept in ckt                     | 06:45:00             | 07:00:00             |                                         |
| 5     | CHP  | CC 104         | ZSS problem                                          | Sensor replaced                                                                   | 08:55:00             | 09:15:00             |                                         |
| 6     | CHP  | PROC-B TO A    | Observed GPL is stopping due to communication issues | established redundant processors communication via new switches and testing done. | 13:30:00             | 14:30:00             |                                         |
| 7     | WT   | co-3           | zss acted                                            | material stuck in cage.                                                           | 09:20:00             | 09:45:00             | cleared material and trail run is taken |