



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 22/08/2026

Incharge(s): Nagendra Midde

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	OLR acted	Reset	18:55:00	19:05:00	
2	OHP	BF 7a	P/C Fuse tb in CJB problem	Replaced	19:30:00	19:45:00	
3	OHP	CO 67	RL1 Loose in sliding contacts	Tightened	16:45:00	17:15:00	
4	CHP	SCR 7	Slew not working	Stacking 30 degree limit acted	16:00:00	16:15:00	
5	CHP	CC 48	Reported red	Control MCB in VFD panel tripped/Reset	17:30:00	17:45:00	
6	CHP	SCR 7	Boom stopped	Stacking 30 degree limit acted /Operator made slew and started boom	19:05:00	19:20:00	
7	CHP	SCR 2 on CC 33	TUL acted	Probe touching the body at cable damage,taping done and given clearance	20:30:00 21:30:00	20:40:00 21:45:00	
8	CHP	CC 47	Reported unhealthy	Control MCB in VFD panel tripped/Reset	21:00:00	21:15:00	
9	WT	OT 5	Drive 1 not resetting	Checking under progress	21:10:00	22:20:00	