



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 10/08/2026

Shift: C

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VS-5	OLR ACTED	RESET DONE	05:25:00	05:35:00	
2	OHP	CO-8	BRS not resetting	Checked and found mechanical BRS not reset.Reset done and tested okay	22:55:00	23:10:00	
3	OHP	WOBR on CO-25	B/C not running	CJD acted.Sensors cleaned and tested okay	00:30:00	00:45:00	
4	OHP	WOBR on CO-6A	B/W fault reset button not working	Adjustment done and tested okay	01:00:00	01:20:00	
5	OHP	BRC on CO-31	B/W-1 not running	MCCB tripped.Made on and tested okay	05:41:00	05:46:00	
6	OHP	BRC on CO-32	Reported B/W's not running	PCRD acted.Released.CT not working.Checked and found CT chain stuck.B/W no problem found	04:00:00	04:20:00	Informed to operation to inform to mechanical
7	CHP	CC-28,F/G	OLR ACTED	RESET DONE	22:15:00	22:20:00	
8	CHP	CC-29,F/G	OLR ACTED	RESET DONE	22:45:00	22:50:00	
9	CHP	CC-104 SCR-9	REPORTED LT AND SLEW NOT WORKING FOUND SLEW MCCB TRIP ,LT LOCAL MODE	SLEW MCCB MADE ON AND LT KEPT REMOTE MODE THAN OK	01:10:00	01:25:00	
10	CHP	CC-31 SCR-1	REPORTED SLEW NOT WORKING LIMIT ACTED DUE TO JAMMING	LIMIT RELEASED AFTER CLEAR THE JAMMING THAN OK	05:10:00	05:20:00	
11	CHP	Cc-51	MPD tripped	Reset done	23:05:00	23:10:00	
12	CHP	Cc-54	Reported tripped	OLR acted.Reset done(2 times)	03:25:00	03:30:00	
13	IOSA	OC-17B	REPORTED STOPPING ON ZSS FOUND ZSS CAGE STUCK UP	ZSS CAGE FREE THAN OK	01:00:00	01:05:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 10/08/2026

Shift: C

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	IOSA	L and T WOBR	REPORTED LT NOT TAKING PLACE	Checked and found M1 thruster brake MPCB tripped.Meggered and found okay.Termination lug loose.Reterminated and tested okay	23:45:00	00:20:00	