वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 26/10/2026

Shift: A

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 34	TRIPPED ON OLR	RESET DONE	06:45:00	06:55:00	
2	OHP	CO 25	TRIPPED ON OLR	RESET DONE	07:10:00	07:20:00	
3	OHP	CO 26	TRIPPED ON OLR	RESETDONE	07:25:00	07:30:00	
4	OHP	CBMS ON CO 2A(TIS 4)	REPORTED RED/NO CONTRO SUPPLY/ CONTROL T/F I/C 415V FUSES BLOWN	FUSES REPLACED AND TESTED OK	07:20:00	08:30:00	NO DELAY/
5	OHP	TBS ON CO 22	RBC LUFFING NOTTAKING PLACE/BRAKE IS MORE	BRAKE GAP ADJUSTED BY MECHANICAL THEN TESTED OK	06:20:00	07:30:00	NO DELAY
6	CHP	CC201	TRIPPED ON OLR	RESET DONE	08:30:00 13:25:00	08:35:00 13:35:00	
7	CHP	CC 203	TRIPPED ON OLR	RESET DONE	08:30:00	08:35:00	
8	CHP	SCR 7 ON CC40	SLEW NOT TAKING PLACE	RETURN FILTER NOT HEALTHY/INFORM TO OPERATION AND MECH	06:30:00	06:40:00	
9	CHP	SCR 7 ON CC40	BC NOT RUNNING/SIGNAL MISSING	LT DONE THEN OK	11:25:00	11:35:00	
10	CHP	SCR 1 ON CC 31	LT NOT TAKING PLACE/DRIVE TRIPPED O OVN FAULT	RESET DONE	12:30:00	12:45:00	
11	WT	OC 1A	REPORTED RED/	PLC POWER RECYCLED THEN OK	10:00:00	10:15:00	