



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 22/06/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	brc on CO 30	bc not running,operator cabin side emergency PB acted	PB released	05:02:00	05:15:00	
2	OHP	VS2	showing red,screen side material jamming,limit acted	reset	04:05:00	04:15:00	
3	OHP	co 34	olr acted	reset	04:10:00	04:15:00	
4	OHP	TT3	not moving,checked main mcb tripped,r phase got cut	proper insulation provided	05:20:00	05:55:00	
5	CHP	CC 39 S2	LT not working,olr acted	reset	03:44:00	03:58:00	
6	CHP	CC 33 scr2	no power,smoke observed near PCRD drum,1 fuse blown in IC ,2 phase not coming in M/C ACB	HT fuse checked 2 fuse ok,megger going on	05:20:00	06:00:00	checking going on
7	CHP	RG1	motor tripped due to rotor jamming	reset	00:40:00	00:50:00	
8	CHP	CC 131	olr acted	reset	01:20:00	01:30:00	
9	CHP	CC 51	mpd acted	reset	01:20:00	01:30:00	2 times
10	WT	co 3(b)	olr acted	reset	00:45:00	00:50:00	
11	WT	OT4	declamp not taking place,oil leakage	informed mechanical	01:50:00	02:00:00	
12	WT	OP2	fwd /rev not taking place,2a3 contactor stucked	2A3 open and fit properly than ok	04:45:00	05:00:00	