



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 20/09/2026

Shift: C

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	tbs on co-22	It not taking place found m-2 olr acted (2times)	reset done	00:30:00 23:00:00	00:40:00 23:10:00	
2	OHP	wobr on co-26	reported It not taking place found plc panel It drive on feedback input fuse blown	glass fuse replaced than ok	23:00:00	00:00:00	
3	OHP	co-25	OLR ACTED (2TIMES)	RESET DONE	00:20:00 05:35:00	00:25:00 05:40:00	
4	OHP	WOBR ON CO-25	REPORTED SLEW NOT TAKING PLACE FOUND SLEW LIMIT ACTED	RELEASED THAN OK	04:00:00	04:20:00	
5	OHP	CO-26	OLR ACTED (3TIMES)	RESET DONE	22:55:00	04:10:00	
6	OHP	CO-29	OLR ACTED	RESET DONE	05:30:00	05:40:00	
7	OHP	CO-10A	OLR ACTED	RESET DONE	05:40:00	05:50:00	
8	OHP	TBS ON CO-22	REPORTED LT BRAKE SUPPLY NOT THERE	LOOSE CONNECTIONS FOUND.TIGHTENED AND TESTED OKAY	05:05:00	05:20:00	
9	CHP	SCR-4 CC-111	REPORTED LT NOT TAKING PLACE FOUND PCRD O/T ACTED	RELEASED THAN OK	23:10:00	23:20:00	
10	CHP	SCR-7 CC-40	REPORTED COMMANDS NOT TAKEN FOUND PLC HANGED	PLC POWER RE-CYCLED THAN OK	04:15:00	04:30:00	
11	WT	OP-4	REPORTED NOT MOVING	D-3 OLR ACTED.RESET DONE	23:10:00	23:20:00	NO DELAY