वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 30/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	Reported RED. OLR acted	Reset done	02:00:00 02:25:00 05:40:00	02:10:00 02:35:00 05:50:00	
2	OHP	TBS ON CO-21	LT not stopping. Checked and found mechanical brake adjustment problem. M-1 tripped	M-1 motor cable disconnected and informed to mechanical	02:00:00	02:40:00	motor to be checked
3	CHP	SCR-7 ON CC-40	B/C not running. Found chute sensor acted due to rain water	water cleaned and made OK	01:00:00	01:15:00	
4	CHP	SCR-1 ON CC-31	Luff not working. checked and found cylinder oil leakage	Informed to mechanical and CCR	01:00:00	01:20:00	No electrical delay