RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 06/11/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	Reported tripped	OLR acted.Reset done(2 times)	06:35:00	07:30:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done(4 times)	07:10:00	13:20:00	
3	OHP	RCO-6A	Reported tripped	OLR acted.Reset done	07:35:00	07:45:00	
4	OHP	BRC on CO-33M	Lt not taking place	M-1 OLR acted.Reset done	08:10:00	08:20:00	
5	OHP	BRC on CO-33M	LT not taking place	PCRD tension acted.Released	08:45:00	09:00:00	
6	OHP	TBS on CO-7A	LT not taking place	Lt selector switch in off condition.Lt not stopping complaint given and found brake adjustment to be done.Electrical side okay	09:00:00	09:15:00	Informed to mechanical for adjustment.Trial taken after adjustment
7	OHP	RSCO-6A	Reported tripped	OLR acted.Reset done	10:00:00	10:10:00	
8	OHP	BRC on CO-31	B/C not running	MPD tripped.Reset done	11:00:00	11:15:00	
9	CHP	CC-27A	Not running in local	TT chute sensor acted.Bypassed to clear jamming.After clearing kept in line	09:15:00	09:30:00	
10	WT	CT-1	Inhaul tripped	MCCB tripped.Made on	11:30:00	11:40:00	
11	IOSA	BRC on OC-15A	Yard to machine interlock zss problem	Probe problem.Bypassed and given clearance	08:45:00	09:00:00	Probe changed after demand.NO delay

वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 06/11/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	IOSA	TBS on OC-14A	LT not taking place	PCRD tension acted.Released	11:30:00	11:40:00	