



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/07/2026

Shift: A

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR -3 ON CO-25	REPORTED NO POWER CHECKED AND FOUND HT CABLE OLD JOINT OPENED INFORMED TO DNW	DNW ATTENDED JOINT DONE POWER CHARGED AND CLEARANCE GIVEN	06:45:00	11:00:00	
2	OHP	WOBR ON CO-26	LT NOT TAKING PLACE FOUND DRIVE TRIP (OVS FAULT)	RESET DONE	07:05:00	07:15:00	
3	OHP	TBS ON CO-21	LT DRIVE TRIP	RESET DONE	07:40:00	07:55:00	
4	OHP	WOBR ON CO-6A	REPORTED B/C NOT RUNNING FOUND CJD ACTED	SENSITIVITY ADJUSTED THAN OK	08:10:00	08:25:00	
5	OHP	BRC ON CO-32	B/W NOT RUNNING ZSS LOOSE CONTACT IN PLC PANEL	TIGHTENED THAN OK	08:55:00	09:15:00	
6	OHP	BRC ON CO-32	CT NOT TAKING PLACE CONTROL SUPPLY LOOSE	TIGHTENED THAN OK	09:15:00	09:50:00	
7	OHP	CO-29	OLR ACTED	RESET DONE	10:05:00 13:50:00	10:15:00 13:55:00	
8	CHP	CC-203	OLR ACTED (2TIMES)	RESET DONE	10:45:00 11:15:00	10:55:00 11:25:00	
9	CHP	CC-37	OLR ACTED	RESET DONE	12:40:00	12:50:00	
10	WT	CP-3	COMMUNICATION PROBLEM	CPU POWER RE-CYCLED THAN OK	10:30:00	10:50:00	
11	WT	CC-3 TO CC-8	POSITION KNOB PROBLEM	PROPERLY FIXED THAN OK	08:25:00	08:50:00	