



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 04/08/2026

Incharge(s): Lal Singh

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC ON CO-34	LT NOT WORKING PCRD OT ACTED	RELEASED	08:20:00	08:30:00	
2	OHP	CO-26	TRIPPED ON OLR	RESET DONE	10:40:00	10:50:00	
3	OHP	TBS ON CO -21	LT NOT WORKING M1 AND M2 TRIPPED	RESET DONE	13:20:00	13:25:00	
4	CHP	CC-28 FG	MPCB TRIPPED	RESET DONE	08:20:00	08:30:00	
5	CHP	CC-104	BRS PROBLEM	BYPASSED ... RECTIFIED AND KEPT IN CKT	06:40:00	07:00:00	
6	CHP	CC-112 SCR-8	BC STOPPING IN ZSS	PROB FIXED PROPERLY	06:45:00	07:10:00	
7	CHP	CC-105 SCR-10	BC STOPPING INBETWEEN	NO ELECTRICAL PROBLEM FOUND	07:00:00	07:30:00	
8	CHP	CC-40 SCR-7	LUFF UP LIMIT STUCK	RELEASED	08:15:00	08:25:00	
9	CHP	CC-33 SCR-2	PCRD DRUM LIMIT ACTED	RESET	10:00:00	10:30:00	
10	CHP	CC-31	NOT HEALTHY MPR NOT RESETTING AND SLIDING CONTACT NOT COMING	CONTACT TIGHTENING DONE AND TESTED ... MOTOR ALSO CHECKED FOUND OK	10:00:00	11:00:00	
11	CHP	CC-29	POSITION IS SHOWING IN CC-31	BYPASS REMOVED	08:25:00	08:35:00	
12	CHP	CC-28	ZSS CAGE STUCK	MADE FREE	09:20:00	09:30:00	
13	WT	OT -2	D-1 TRIPPED ON PGF FAULT	RESET DONE	07:25:00	07:30:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/08/2026

Incharge(s): Lal Singh

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	WT	OAF-2A	RUN FEEDBACK IS THERE BUT PHYSICALLY NOT RUNNING	CHECKED NO ELECTRICAL PROBLEM FOUND ... DRIVE PARAMETERS ADJUSTED FOR MOTOR PROTECTION	11:30:00	12:00:00	