



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/08/2026

Incharge(s): G Eswara Rao

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 111	TRIPPED ON OLR	RESET DONE	14:40:00	14:55:00	
2	OHP	TBS ON CO 20	LBC ZSS ACTING/PROBE GOT DAMAGED	ZSS ROBE REPLACED	18:30:00	19:00:00	
3	OHP	CO 26	TRIPPED ON OLR	RESET DONE	20:20:00	20:30:00	
4	OHP	CO 34	TRIPPED ON OLR	RESET DONE	20:00:00	20:05:00	
5	OHP	CO 34A	BRS ACTING/WIRE S LOOSE AT SENSOR	SENSOR WIRES TIGHTEN THEN OK	16:00:00	16:30:00	MEAN WHILE BYPASSED
6	OHP	CO 26	TRIPPED ON OLR	RESET DONE	21:25:00	21:35:00	
7	CHP	SCR 2 ON CC33	BW NOT RUNNING/DRIVE TRIPPED ON OLR	RESET DONE	15:45:00	15:50:00	
8	CHP	SCR 2 ON CC 33	LT NOT TAKING PLACE/PCRD ZSS ACTED	RESET DONE	18:35:00	18:45:00	
9	CHP	SCR 7 ON CC40	SLEW NOT WORKING/MATERIAL JAMMING	INFORM TO OPERATION	18:55:00	19:00:00	
10	CHP	CC 114	PC ACTED	RESET DONE	15:50:00	16:05:00	