वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 20/10/2026

Shift: B

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	OLR acted	reset done	16:30:00	16:50:00	
2	OHP	CO-34	OLR acted due to overload	Reset done	16:50:00 17:05:00 17:40:00	17:00:00 17:15:00 17:45:00	
3	OHP	VF-1A	M-1 MPCB tripped	Reset done	20:10:00	20:20:00	
4	OHP	CO-26	OLR acted	Reset done	20:25:00	20:30:00	
5	OHP	BRC ON CO-28	Lt not working. Found PCRD MPCB tripping on command. Motor meggering done and found OK	After removing two phase cable outgoing from contactor, MPCB is holding. Loop provided and checking is under progress	19:15:00	20:15:00	
6	CHP	CC-110	ZSS acting. Found loose contact in module	Properly tightened and made OK	18:00:00	18:15:00	
7	CHP	SCR-3 ON CC-37	LT not working. Drive tripped	Reset done	19:40:00	19:50:00	
8	CHP	CC-51	MPR tripped to stop feeding conveyor	Reset done	17:00:00	20:45:00	5 times