



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 13/05/2026

Area: OHP

Equipment	Job
tbs-2 on co-20	running inspection is done. and defect list made ready
repair bay HT transformer	The tank base leakage welding job is in progress.
cr-1,2,3 level	lighting is improved.
lc-6 sump pump	pipeline fixing done and connected to sump pump outlet.
1-141lc3,lc4 ground floor ; 1-14lc7 ; om-15,om-16	housekeeping is done.
om-16,24,1-15lc2,1-141lc3,1-141lc4 ground floor RIO	ario ppm is done.
co-8,11	panel side ppm is done.
co-76r,18	panel and motor side ppm is done.
co-14 pullchord	cable got rub due to return idler missing, joint done after fixing of idlers and kept back in circuit.
brc-1 on co-28	Bridge conveyor motor checked, current checked, found normal, LT speed is increased from 100 rpm to 150 rpm on operation requirement. BC ZSS preparation is under progress. Panels Blowing is done.
brc-3 on co-33m	shifted from co-33m to co-34