



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 31/07/2026

Incharge(s): G Eswara Rao, M Kailash

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT-3	PCRD cable got stuck when doing placement. Main MPCB tripped	Reset done and made OK	00:10:00	00:30:00	
2	OHP	TT-3	on CO-22 Position missing. Checked and found Glass fuse blown.	Fuse replaced and made OK	01:00:00 03:35:00	01:30:00 03:50:00	Bypassed in I/O rack
3	OHP	TBS ON CO-20	Lt not working. PCRD tension acted	Released and made OK	00:15:00	00:30:00	
4	OHP	CO-26	Tripped on Overload	Reset done	04:15:00	04:25:00	
5	OHP	CO-25	Tripped on Overload	Reset done	04:45:00 05:15:00	04:55:00 05:25:00	
6	CHP	STK-2 ON CC-35	yard conveyor not starting after boom conveyor started.	Signal missing. LT done and then OK	00:10:00	00:20:00	
7	CHP	CC-52	MPR tripped on overload	Reset done	03:35:00 03:50:00	03:40:00 03:55:00	
8	CHP	CC-51	Feeding conveyor tripped on Overload	Reset done	04:35:00 05:20:00	04:40:00 05:25:00	