



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/09/2026

Shift: C

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCo 10 a	C/S yard side Return core loose	Tightened	05:10:00	05:30:00	
2	OHP	CO 34 ZSS	Cage stuck	Made it free	23:40:00	23:55:00	
3	OHP	CO 111	MPCB trip	Made it on	23:50:00	00:05:00	
4	OHP	CO 26	OLR acted	Reset	02:10:00	05:40:00	4 times
5	OHP	CO 6a	Receiver Sensor Problem	Bypassed	02:40:00	02:55:00	
6	OHP	CO 29	OLR Acted	Reset	05:20:00	05:30:00	
7	CHP	SCR 3 on CC 37	Luff Limit Stuck	Made it free	01:30:00	01:50:00	
8	CHP	SCR 9 on CC 104	LT Drive Tripped	Reset	02:30:00	02:45:00	
9	CHP	SCR 10 on CC 105	HT Breaker was off on the machine	Made it on	00:00:00	01:00:00	
10	CHP	CO 2 ZSS	Cage c clamp problem	Replaced	03:30:00	04:00:00	
11	CHP	CC 131	OLR acted	Reset	01:10:00	01:15:00	
12	CHP	RG3	Temperature Scanner Neutral missing	Tightened	04:15:00	04:25:00	
13	WT	OC 1a	Zss probe damaged	Replaced	01:15:00	01:45:00	