



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 10/06/2026

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment    | Problem                                     | Action                              | From     | To       | Remarks |
|-------|------|--------------|---------------------------------------------|-------------------------------------|----------|----------|---------|
| 1     | OHP  | TBS on CO-7A | Left luff going down when giving up command | Brake adjustment done by mechanical | 14:20:00 | 14:40:00 |         |
| 2     | OHP  | CO-26        | Reported tripped                            | OLR acted.Reset done                | 14:50:00 | 15:00:00 |         |
| 3     | CHP  | Cc-38 SCR-5  | B/C not running                             | Slewing 30 degree limit acted.      | 14:45:00 | 15:00:00 |         |
| 4     | CHP  | CC-38 SCR-5  | LT not taking place                         | Drive tripped.Reset done            | 16:35:00 | 16:50:00 |         |