



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 09/06/2026

Area: OHP

Equipment	Job
co-3B, 4A, H/E area	Hoist panel, LDB maintenance is done. co-3b gallery lighting is improved.
vf-10 spare motor	overhauling done, bearings replaced, trail run to be taken.
co-35a brs	sensors , cable replacement under progress.,
co-65, 68	motor and panel side ppm is done.
DE-5 RAL-2	RAL-2 tripped due to overload , after EnMD clearance, reset done trail run is taken and Currents checked.
co-11A, , and H/E hoist ; RBF-1a,2a,3a ; RSCO-2a ; TT-4	motor and panel side ppm is done.
Yard Machine spare transformer	Ht termination side oil leak was observed. tightened properly and checked , leak arrested. Oil leak not found anywhere else.
wobr-1 on co-26; co-26 ; wob-4 on co-6a ; co-6a	ppm is done
tbs-7 on co-19	Thruster brake mechanism is not working, supply is available .to be checked further.
TBS-6 on co-7a	LBC motor and panel side checking is done, DMPR settings also checked, changed as required.
tbs-1 on co-22	shifted to co-23