



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/08/2026

Incharge(s): G Eswara Rao, K SANKARA RAO

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	OLR ACTED	RESET DONE	08:10:00	08:20:00	
2	OHP	CO-25	OLR ACTED	RESET DONE	09:10:00	09:20:00	
3	OHP	BF-3A	STOPPING ON ZSS FOUND ZSS GAPE PROBLEM	PROBE GAPE ADJUSTED THAN OK	09:35:00	09:50:00	
4	OHP	BRC ON CO-33M	REPORTED LT NOT TAKING PLACE FOUND M-1 OLR ACTED (DUE TO TRACK JAMMING)	RESET DONE AND INFORMED TO OPERATION	11:30:00	11:50:00	
5	CHP	CC-40 SCR-7	B/C OLR ACTED (DUE BELT SLIP) INFORMED TO MECHANICAL	RESET DONE	10:15:00	11:00:00	
6	CHP	CC-220	REPORTED STOPPING ON ZSS FOUND ZSS MODULE PROBLEM	ZSS MODULE REPLACED WITH NEW ONE THAN OK	11:45:00	12:00:00	
7	CHP	CC-54	MPD TRIP (3TIMES)	REST DONE	10:05:00	10:20:00	
8	CHP	CC-131	OLR ACTED	RESET DONE	12:55:00	13:00:00	
9	CHP	CC-18	BRS ACTED	RESET DONE	10:45:00	10:55:00	
10	CHP	CC-201	OLR ACTED	RESET DONE	10:42:00	10:50:00	