वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 15/10/2026

Shift: B

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | TBS ON CO-22 | Right luff not working. Overload acted | Reset done | 14:15:00 | 14:30:00 | |
| 2 | OHP | CO-10A | Overload acted | reset done | 15:15:00 | 15:20:00 | |
| 3 | OHP | BRC ON CO-8A | Oil pump feedback fault. Control desk Reset not done | reset done and made OK | 17:30:00 | 17:45:00 | |
| 4 | OHP | CO-11A | BRS acting frequently. Checked with empty belt and with load | No complaint found. | 17:30:00 | 18:30:00 | No delay |
| 5 | OHP | BRC ON CO-32 | LT complaint. PCRD tension acted | Released and made OK | 20:40:00 | 20:50:00 | |
| 6 | OHP | BRC ON CO-8A | Oil temperature high trip. Found Bucket wheel pump contactor welded and MCCB tripped | Tips changed from spare feeder and tested OK | 20:30:00 | 21:10:00 | |
| 7 | OHP | WOBR ON CO-29 | Luff not working. | Checking is under progress | 21:10:00 | 22:00:00 | |
| 8 | OHP | CO-26 | Overload acted | Reset done | 17:00:00<br>21:30:00 | 17:10:00<br>21:45:00 | |
| 9 | CHP | CC-51 | Feeding conveyor tripped on overload | Reset done | 17:30:00<br>18:20:00 | 17:35:00<br>18:25:00 | |
| 10 | CHP | CC-52 | Tripped on overload | Reset done | 21:00:00 | 21:05:00 | |
| 11 | IOSA | WOBR ON OC-17A | ZSS probe failed | Probe changed | 15:50:00 | 16:10:00 | |