वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 19/10/2026

Shift: B

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-15	Healthy stop. TT position sensor plate moving.	Fixed properly	17:00:00	17:15:00	
2	OHP	CO-25	OLR acted	Reset done	17:20:00	17:35:00	
3	OHP	VF-10A	OLR acted	Reset done	18:20:00	18:30:00	
4	OHP	WOBR ON CO-6A	Bucket wheel not rotating. Mechanical problem	Informed to mechanical	18:30:00	18:40:00	
5	OHP	CO-26	OLR acted	Reset done	19:10:00 21:35:00	19:20:00 21:45:00	
6	OHP	BRC ON CO-8A	LT not working. Drive tripped	Reset done	19:20:00	19:35:00	
7	OHP	CO-34	OLR acted	Reset done	19:30:00 19:55:00	19:40:00 20:00:00	
8	OHP	BRC ON CO-31	Boom Conveyor not running. OLR acted	Reset done	21:30:00	21:40:00	
9	CHP	SCR-7 ON CC-40	Overload trip	reset done	16:30:00 19:10:00	16:40:00 19:20:00	
10	CHP	Transfer Car	Old joint flash observed after machine shifting and while transfer car is going to parking.	Joint opened and re lugging done. Proper wrapping provided	14:00:00	17:00:00	