



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/08/2026

Incharge(s): G Eswara Rao, K SANKARA RAO

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	OLR ACTED	RESET DONE	07:10:00	07:15:00	
2	OHP	RSCO-6A (C)DRIVE	OLR ACTED	RESET DONE	10:45:00	10:50:00	
3	OHP	RCO-6A	OLR ACTED	RESET DONE	11:25:00	11:30:00	
4	CHP	CC-58	CURRENT SP FAULT TRIP	RESET DONE	12:25:00	12:40:00	
5	CHP	CC-52	MPD TRIP (FEEDING CONVEYOR STOP)	RESET DONE	13:00:00	13:05:00	
6	CHP	CC-54	REPORTED BRS NOT HEALTHY FOUND GLASS FUSE BLOWN IN MODULE	GLASS FUSE REPLACED THAN OK	11:15:00	11:30:00	
7	CHP	CC-40 SCR-7	LUFF NOT WORKING MPR TRIP	RESET DONE	09:30:00	09:40:00	
8	CHP	CO-111	BRS ACTED	RESET DONE	07:50:00	08:00:00	
9	CHP	CC-40 SCR-7	LUFF NOT WORKING FOUND MCCB AUX BLOCK PROBLEM	AUX BLOCK REPLACED THAN OK	10:30:00	10:45:00	
10	CHP	CC-36 S-1	LT M-1 OLR ACTED	RESET DONE	11:25:00	11:40:00	
11	CHP	CC-36 S-1	B/C ZSS PROBLEM	ZSS MODULE SPEED ADJUSTED THAN OK	11:25:00	11:40:00	
12	WT	OT-1	DRIVE-2 OCA FAULT TRIP CHECKED AND FOUND M-2 BURNT	MOTOR REPLACED DIRECTION CHECKED AND CLEARANCE GIVEN THAN OK	09:40:00	14:20:00	
13	IOSA	OC-14A	REPORTED HEALTHY STOP	PULL CHORD HARD-WARE BYPASSED THAN OK	09:50:00	10:10:00	