



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 28/08/2026

Incharge(s): Lal Singh

Shift: C

| Sl No | Area | Equipment    | Problem                          | Action                                                       | From     | To       | Remarks |
|-------|------|--------------|----------------------------------|--------------------------------------------------------------|----------|----------|---------|
| 1     | OHP  | WBR ON CO-25 | LT M4 TRIPPED                    | RESET DONE                                                   | 01:10:00 | 01:25:00 |         |
| 2     | OHP  | CO-26        | TRIPPED ON OLR                   | RESET DONE                                                   | 01:30:00 | 01:40:00 |         |
| 3     | OHP  | WBR ON CO-26 | LT AND SLEW NOT WORKING          | LT M4 RESET ... SLEW DRIVE RESET                             | 03:40:00 | 03:55:00 |         |
| 4     | OHP  | CO-25        | OLR ACTED                        | RESET DONE                                                   | 04:25:00 | 04:30:00 |         |
| 5     | CHP  | CC-52        | TRIPPED 2 TIMES                  | RESET DONE                                                   | 01:50:00 | 02:40:00 |         |
| 6     | CHP  | CC-54        | MOTOR TRIPPED ON OLR             | RESET DONE                                                   | 05:00:00 | 05:10:00 |         |
| 7     | IOSA | WOBR L and T | LT NOT WORKING                   | PROGRAM CHANGED ... WIRING ALSO CHANGED ACCORDINGLY ..TESTED | 22:00:00 | 01:30:00 |         |
| 8     | IOSA | BRC          | CT DRIVE TRIPPED ON OVER CURRENT | RESET DONE                                                   | 04:45:00 | 05:05:00 |         |
| 9     | IOSA | OC-14A       | MASTER TRIP RELAY ACTED          | RESET DONE AND TESTED                                        | 23:15:00 | 23:30:00 |         |