



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 27/06/2026

Incharge(s): Lal Singh

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WBR ON CO -29	LUFF OLR ACTED	RESET DONE	22:35:00	22:45:00	
2	OHP	CO-29	TRIPPED ON OLR	RESET DONE	23:00:00	23:10:00	
3	OHP	CO-32 BRC	LT SKEW ACTED	INFORMED MECH	01:45:00	02:00:00	
4	OHP	CO-19 TBS	CRMP SIDE THRUSTER BREAK MPCB TRIPPING ...LEFT LUFF OLR ACTED .. CJD ACTED BECAUSE OF NOT FIXING PROPERLY AT TIME OF GATE CHANGE	BREAK DISCONNECTED .. LUFF OLR RESET .. CJD FIXED PROPERLY	03:25:00	03:45:00	
5	OHP	CO-25	TRIPPED ON OLR	RESET DONE	04:55:00 05:25:00	05:05:00 05:35:00	
6	OHP	CO-26	TRIPPED ON OLR	RESET DONE	03:55:00	04:05:00	
7	CHP	CC-106 SCR -9	BC NOT RUNNING IN REC MODE	STOP SIGNAL FROM CPP	22:20:00	22:35:00	
8	CHP	CC-107	TRIPPED ON OLR	RESET DONE	01:00:00 03:25:00	01:05:00 03:30:00	
9	CHP	CC-58	TRIPPED ON DMPR	RESET DONE	01:10:00	01:25:00	