



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/06/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CR 1A	lubrication pump not healthy	reset	02:50:00	02:59:00	
2	OHP	CO 25	OLR acted,motor taking upto140 Amp	motor checked found ok,gear box side some problem,OLr reset	01:30:00	01:40:00	5 times
3	OHP	co 86	OLR high not coming,MCCB aux contact problem	MCCB aux contact bypass	23:00:00	23:10:00	
4	OHP	RSCO 10 A (C)	olr acted	reset	22:30:00	22:45:00	
5	OHP	BRC on co 28	b/w 1 not running,olr acted	reset	03:50:00	04:10:00	
6	OHP	co 26	olr acted	reset	23:55:00	00:05:00	
7	CHP	CC 131	Motor tripped on OLR	reset	03:55:00	04:00:00	
8	CHP	RG2	CTMF relay not showing healthy	reset	22:15:00	22:25:00	
9	CHP	CC 38 SCR5	LT not working,track jamming,M5 mpcb tripped	made it on,informed operation	22:35:00	22:45:00	
10	CHP	CC 33 SCR2	LT not working,PCRD sensor acted	reset	02:20:00	02:30:00	
11	CHP	CC 105 SCR10	B/C not running	wrong complaint	04:05:00	04:10:00	
12	CHP	CC 107	conveyor not running,oil leakage from fluid coupling	informed operation	04:40:00	04:50:00	