



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/07/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-16	Reported not healthy	PC acted.	15:45:00	15:55:00	Released by operation after informing
2	OHP	BRC on CO-34	B/W-1 not rotating	Mechanical guide roller problem	18:00:00	18:15:00	
3	OHP	CO-26	Reported tripped	OLR acted.Reset done	19:10:00	19:20:00	
4	OHP	CO-29	Reported tripped	OLR acted.Reset done	19:30:00	19:40:00	
5	CHP	CC-203	Reported tripped	OLR acted.Reset done	16:30:00	16:35:00	
6	CHP	CC-111 SCR-8	LT not taking place	Remote/Local cable loose at PLC panel.Tightened and checked tested okay	18:40:00	19:15:00	
7	CHP	CC-215	Cs acted	Due to fumes from boiler coal.	19:10:00	19:25:00	Informed to operation
8	WT	OT-5	Reported hydraulic cooling fan not running	Checked and found PLC output relay contact high missing.Given and tested okay	14:00:00	16:00:00	NO delay due to no rake
9	WT	OP-10	Reported not moving	Checked and found communication okay but command not coming to tippler PLC.High missing at Joystick.Cable loop provided from PLC room and tested okay	18:00:00	22:00:00	NO delay as OP-9 was available for tipping and rake tipping was done