



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/07/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-29	Reported luffing not taking place	OLR acted.Reset done	02:15:00	02:30:00	
2	OHP	CO-21	ZSS acted	Due to cage got tilted upwards and got stuck between idler and belt.Made free and tested okay	03:05:00	03:40:00	
3	OHP	VS-2A	Reported tripped	OLR acted.Reset done	03:55:00	04:10:00	
4	OHP	TIS-2	Reported red	Power recycled and tested okay	02:35:00	02:50:00	
5	OHP	BRC on CO-32	Reported B/C not running	Emergency acted at operator cabin top.Released and tested okay	01:35:00	01:55:00	
6	OHP	BRC on CO-32	Reported HMI display not working and hydraulic pump not running	Ethernet cable not connected at HMI.Connected and Pump output relay A1 contact loose.Tightened and tested okay	01:35:00	01:55:00	
7	CHP	Cc-107	Reported tripped	OLR acted.Reset done	03:30:00	03:35:00	