



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/08/2026

Incharge(s): K SANKARA RAO

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-33M	Overload acted	Reset done	11:15:00	11:20:00	
2	OHP	WOBR ON CO-29	LT not taking place. Found M3 Overload acted	Reset done	10:15:00	10:30:00	
3	OHP	CO-4A	Control supply Healthy bit missing in PLC.	Bypassed in panel TB and given clearance	13:00:00	13:30:00	
4	CHP	CC-104 SCR-9	Bucket wheel not running. Checked and found Oil level low.	Informed to mechanical	08:45:00	09:15:00	
5	CHP	CC-131	Overload acted.	Reset done	10:30:00 13:10:00	10:35:00 13:15:00	
6	WT	OT-3	Drive-1 tripped on 43-encoder fault	reset done	08:20:00	08:25:00	