



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 18/05/2026

Shift: A

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	TRIPPED ON OLR	RESET DONE	06:30:00 07:05:00	06:40:00 07:15:00	
2	CHP	CC 201	TRIPPED ON OLR	RESET DONE	12:45:00	12:50:00	
3	CHP	CC 203	TRIPPED ON OLR	RESET DONE	12:45:00	12:55:00	
4	CHP	CC 29	ZSS ACTED/PROBE PROBLEM	BYPASSED	13:00:00	13:10:00	PROBE TO BE CHANGED
5	CHP	CC 54	TRIPPED ON OLR	RESET DONE	07:20:00	07:27:00	
6	CHP	CC 51A	TRIPPED ON OLR	RESET DONE	07:20:00	07:30:00	
7	CHP	CC 51A	TRIPPED ON OLR	RESET DONE	09:50:00	09:55:00	
8	CHP	CC 131	TRIPPED ON OLR	RESET DONE	12:40:00	12:50:00	
9	CHP	CC 21 C/D	TRIPPED ON MPCB DUE TO JAMMING	MPCB MADE ON	13:25:00	13:30:00	
10	CHP	CC 112	BC SIGNAL CHANGING FROM GVM TO OHP SIDE REQUEST	SIGNAL GIVEN	13:55:00	14:10:00	
11	WT	OP 2	F/ REVERSE NOT TAKING PLACE/ B TYPE ISOLATOR B PHASE O/G TERMINATION GOT MELTED AND SINGLE PHASEING	B TYPE ISOLATOR KEPT OFF AND TROLLY LINE SECTION BYPASSED THEN GIVEN CLEARANCE	06:00:00	07:15:00	