



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/05/2026

Incharge(s): Lal Singh

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	TRIPPED ON OLR	RESET DONE	01:25:00 02:55:00	01:35:00 03:05:00	
2	OHP	CO-25	TRIPPED ON OLR	RESET DONE	02:50:00	03:00:00	
3	OHP	CO-68	BRS NOT RESETTNG ...SENSOR CABLE CUT	FIRST BYPASSED ... LATER CABLE CHANGED AND KEPT IN CKT	00:15:00	00:50:00	
4	CHP	CC-33 SCR-2	SLEW NOT WORKINGSLEW AREA JAMMING	INFORMED FOR CLEANING	01:10:00	01:20:00	
5	CHP	CC-31	SLEW DRIVE TRIPPED	RESET DONE	04:25:00	04:40:00	
6	CHP	CC-52	MPD TRIPPED ON OL	RESET DONE	00:50:00	00:55:00	
7	CHP	CC-58 TT	POSITION SIGNAL NOT COMING	CONTROL FUSE REPLACED THEN OK	05:00:00	05:20:00	
8	WT	OP-2	BREAKER TRIPPED	CHECKED PADS ARE OK .. BREAKER MADE ON AND TESTED	05:35:00	05:40:00	
9	WT	CP-2	BREAKER TRIPPED	CHECKED AND MADE ON	05:45:00	05:55:00	