



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 21/09/2026

Shift: A

Incharge(s): G Eswara Rao

| Sl No | Area | Equipment      | Problem                                                                                                   | Action              | From                 | To                   | Remarks |
|-------|------|----------------|-----------------------------------------------------------------------------------------------------------|---------------------|----------------------|----------------------|---------|
| 1     | OHP  | co 26          | tripped on olr                                                                                            | reset done          | 08:40:00<br>13:15:00 | 08:50:00<br>13:20:00 |         |
| 2     | OHP  | WOBR ON CO 26  | CABIN ADJUSTMENT NOT WORKING/MPCB TRIPPED                                                                 | MPCB MADE ON        | 07:30:00             | 07:40:00             |         |
| 3     | OHP  | VS 4A          | TRIPPED ON OLR                                                                                            | RESET DONE          | 06:50:00             | 07:00:00             |         |
| 4     | OHP  | VS 3A          | TRIPPED ON OLR                                                                                            | RESET DONE          | 08:55:00             | 09:05:00             |         |
| 5     | OHP  | CO 10A         | TRIPPED ON OLR                                                                                            | RESET DONE          | 09:25:00<br>12:40:00 | 09:35:00<br>12:50:00 |         |
| 6     | OHP  | CO 8           | TRIPPED ON OVER CURRENT (IMB FAULT)/CHECKED AND FOUND RESISTANCE and INDUCTANCE LOW VALUES SMOKE OBSERVED | MOTOR TO BE CHANGED | 11:25:00             | 13:30:00             | 3TIMES  |
| 7     | OHP  | TBS ON CO 5A   | NO DRIVES RUNNING/CONTROL TRIPPED                                                                         | CONTROL MADE ON     | 12:00:00             | 12:15:00             |         |
| 8     | CHP  | SCR 4 ON CC111 | LT NOT TAKING PLACE/PCRD TENSION ACTED                                                                    | TENSION RELEASED    | 07:45:00             | 08:00:00             |         |
| 9     | CHP  | SCR 2 ON CC33  | BW NOT WORKING/OLR ACTED                                                                                  | RESET DONE          | 09:35:00             | 09:50:00             |         |
| 10    | CHP  | SCR 3ON CC37   | LT NOT TAKING PLACE/DRIVE TRIPPED                                                                         | RESET DONE          | 10:10:00             | 10:25:00             |         |
| 11    | CHP  | CC 48          | C/S ACTED DUE TO CHUTE JAMMING                                                                            | INFORM TO OPERATION | 10:35:00             | 10:55:00             |         |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 21/09/2026

Incharge(s): G Eswara Rao

Shift: A

| Sl No | Area | Equipment | Problem        | Action     | From     | To       | Remarks                     |
|-------|------|-----------|----------------|------------|----------|----------|-----------------------------|
| 12    | CHP  | CC 52     | TRIPPED ON OLR | RESET DONE | 09:00:00 | 09:10:00 | FEEDING<br>CONV.<br>STOPPED |