



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 02/08/2026

Shift: B

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-50	DMPR tripped on OLR	reset done	16:40:00	16:55:00	
2	OHP	WOBR-2 on co-29	BW motor replaced	Trail run is taken and currents recorded	14:00:00	15:45:00	
3	OHP	BRC-2 ON CO-31	reported CT not taking place	Cabin side End limit switch got stuck . made free and trail run is taken.	20:10:00	20:20:00	
4	OHP	wobr-3 on co-25	LT not taking place	M4 tripped, M3 brake cable got cut, rejoin done. Brakes were found tightened, regulation of brakes was done along with Mechanical.	17:10:00 17:30:00	17:20:00 18:00:00	
5	OHP	co-26	tripped on olr twice	reset done	15:50:00 17:15:00	16:00:00 17:45:00	
6	CHP	CC 52	Feeding conv OLR acted	Reset	17:15:00	17:20:00	
7	CHP	CC 55	OLR acted	Reset	19:20:00	19:30:00	
8	CHP	CC 131	OLR acted	Reset	19:20:00	19:25:00	
9	CHP	CC 51	Feeding conv Olr acted	Reset	16:00:00	16:05:00	
10	WT	CO 3 Red	C/S power cable got	Rejoined	19:50:00	20:05:00	
11	IOSA	oc-7b	healthy stopped	no problem found	19:20:00	19:40:00	