



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/08/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	OT-3	Motor drive end cover bolts loose	Bolts tightened and tested okay	15:00:00	15:15:00	
2	OHP	CO-51	Reported tripped	OLR acted.Reset done	15:00:00	15:08:00	
3	OHP	CO-26	Reported tripped	ORL acted.Reset done(3 times)	16:50:00	19:35:00	
4	OHP	BRC on CO-8A	Yard interlock signal missing	Interlock yard ZSS probe problem	20:00:00	22:00:00	TO be changed when CO-8A stops
5	CHP	CC-132	Reported PC not healthy	LR PC acted.Reset done and tested okay	16:30:00	16:40:00	
6	CHP	CC-33 SCR-2	LT not taking place	PCRD drum sensor acted.Reset done and tested okay	19:10:00	19:25:00	
7	WT	OC-1A	ZSS acted	Found material jamming	21:00:00	21:15:00	