



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/08/2026

Shift: C

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR ON CO-25	REPORTED LT NOT TAKING PLACE FOUND M-4 OLR ACTED (DUE TO TRACK JAMMING)	RESET DONE	23:10:00	23:20:00	
2	OHP	RSCO-1A	REPORTED PC NOT HEALTHY CHECKED AND FOUND GLASS FUSE BLOWN IN CJB	FUSE REPLACED THAN OK	22:40:00	23:00:00	
3	CHP	CC-37 SCR-3	REPORTED LT NOT TAKING PLACE FOUND DRIVE TRIP	RESET DONE	00:55:00	01:10:00	
4	CHP	CC-52	MPD TRIP	RESET DONE	01:20:00	01:25:00	
5	CHP	CC-51	MPD TRIP	RESET DONE	01:25:00	01:30:00	