



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/09/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	Unhealthy. OLR acted	Reset done	20:00:00	20:20:00	
2	OHP	WOBR on CO-26	Luffing not working. MPCB tripped	Reset done	17:30:00	17:45:00	
3	OHP	TBS on CO-7A	Spark observed at the cable tray near operator cabin	Damaged cable part removed and proper jointing done	20:30:00	21:30:00	No delay
4	OHP	CO-111	Reported tripped	OLR acted.Reset done	15:15:00 15:25:00	15:25:00 15:35:00	
5	OHP	WOBR on CO-6A	Interlock ZSS	Probe changed and tested okay	18:00:00	19:00:00	NO delay as machine was in shutdown
6	OHP	VS-2	Reported tripped	OLR acted.Reset done	21:40:00	21:45:00	
7	OHP	CO-5	Cable lug damaged while terminating	After alignment during motor termination one phase lug got damaged.Replaced and tested okay	21:10:00	21:30:00	No delay
8	CHP	CO-2	ZSS acted	Due to belt piece hanging.Material stuck up inside cage	18:50:00	19:10:00	Infomed to operation
9	CHP	CC-104 SCR-9	LT not taking place	Drive tripped.Reset done	19:30:00	19:45:00	
10	CHP	CC-45	ZSS acted	Probe got directed.Probe directed	20:55:00	21:20:00	
11	WT	OC-1A	ZSS acted	Due to jamming	15:15:00	15:35:00	